



3000 and 4000 Series QVR Firmware V3.4.80 Build 170302 Release Notes

Supported models:

ALI-QVR3004H

ALI-QVR3008H

ALI-QVR3016H

ALI-QVR4008H

ALI-QVR4016H

Fixes and improvements:

1. Changed to new password logic where recorder needs to be activated with a new password during initial setup
2. Added new self-reset password options
3. Added support for 5 inputs signals (TVI, AHD, CVI, CVBS, IP)
4. Added auto TVI/CVI/AHD/CVBS detection for all inputs
5. Added 3MP TVI support on specific inputs for 3000 series recorders
 - a. ALI-QVR3004H – Input 1
 - b. ALI-QVR3008H – Inputs 1, 2
 - c. ALI-QVR3016H – Inputs 1, 2, 3, 4
6. Updated Web Component signature code
7. Changed default display resolution to 1280*720
8. Added Guarding Vision platform access
9. Added cloud firmware update option
10. Removed Simpleddns from ddns options
11. Changed UPnP to be Enabled by default
12. Added Event Stream setting capabilities through web client access
13. Added Notify Surveillance Center linkage option to send real time alerts to the ACMS client software and mobile applications
14. Added Holiday Schedule recording option
15. Resolved issue of a factory default potentially occurring if the device loses power
 - a. ALI-QVR3016H
16. Resolved camera drop line issue where groups of cameras will randomly lose a video connection to the recorder
 - a. ALI-QVR3016H
17. Added .avi file export option from the local GUI drop down choices